Work Orde Wednesday, Octo			PM								(Page 1
Revision ID:	D3690-041				Accept				s	etup Star Stop		
	Glareshield Ass 10/27/2010 11/11/2010	sembly Start Qt Req'd Q	-			Cust Item II Customer:	D:			Stop	'	
Approvals:	Process Plan	n:	H	Date/ <i>D/O-J S</i>	Tooling: SPC (Y/N):		te:		R	aun Star Stop		
Sequence ID/ Work Center II		Operation Descript			Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr D3690	Revi Rev	ision Nbr B				•			(2V))		
100 		Pick Kit	Memo	. *	0.00	m. Lu	s/ul	16				
110 		Small Fab	Memo 1- transfer D3690□2-	drill D3697-041 and D3698- - scribe bath # and part # as p	0.00 0.00 1 in D3690-1 and asser er dwg	mble as per dwg	m, j	l	ls/u/	(2x) 17)	-,

120 QC

Memo

QC5- Inspect part completeness to step on W/O

Quality Control

Dart A	erospace	Ltd
--------	----------	-----

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	DCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								İ	
Part No		PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	4:	_ Date:	
		esolution:							
NCR:		\	WORK ORD	ER NON-CONFORMA	NCE (NCI	7)			
DATE	STEP	Description of NC	Initial		Section B otion Sign &		ation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Date		on C	Chief Eng	QC Inspector
					:				
							-		

Wednesday, October 27, 2010 4:03:47 PM

Item ID:

D3690-041

Accept



Setup Start

Stop



Revision ID:

Item Name:

Glareshield Assembly

Start Date:

Required Date: 11/11/2010

10/27/2010

Start Qty: 2.00

Req'd Qty: 2.00



Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Process Plan:

Operation

Description

SprayPaint

Date: _____

Date:

Tooling: SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Tool # Plan

Code

Run Start

Reject

Otv

Accept Qty

Stop

Reject

Number Stamp

Insp.

Sequence ID/ Work Center ID

130

SprayPaint

Spray Painting

Memo

0.00

0.00

1- Mask hatched areas (6 pls) on inside of the part prior to painting as per dwg 2-Paint D3690-041 assy flat black using Basf Glasurit 22 Line code

SFA39.50 per Dart OSI 005 4.2

140

QC

Quality Control

QC14- Inspect Spray Paint

Memo

0.00

0.00 PDP63357 Colopolos

4 10-12-01

160

QC

Ouality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/12/014/ PS10-12-1 (2)

Dart Aerospa	ace Ltd
--------------	---------

W/O:			W	ORK ORDER CHANG	ES						
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
	!										
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes 1	No DQA:	Date: _				
					QA: N/C Closed: Date:						
NCR:		V	VORK ORD	ER NON-CONFORMA	ANCE (NCR)						
DATE	STEP	Description of NC		Corrective Action Sect		Verification	Approval	Approval			
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector			
		í									
						,					

Picklist Print

Wednesday, October 27, 2010 4:03:51 PM

Work Order ID: 63352

D3690-041 Parent Item:

Parent Item Name: Glareshield Assembly



Start Date: 10/27/2010

Required Date: 11/11/2010

Start Qty: 2.00

Required Qty: 2.00

Comments:

IPP Rev:A 08-04-29 new issue DD verified by:ec

IPP Rev:B 08-07-14 revB as per dwg DD verified by:ec IPP Rev:C 08-09-08 added painting DD verified by:EC IPP Rev:D 08-10-07 revC as per dwg DD verified by:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN960JD3	HI III III	Purchased	No		4.44		Each	140.0000	2	4 M	h	u/11/1	6
				Location ST346	/	Loc (<u>Otv</u> 140	Loc Code				·	
CR3213-4-03	•	D 1 1	No		107989		140 Each	74.0000	35	4 X	- -		
rivet		Purchased	No				Eacn	74.0000		70 M	7-/	isfu	116
					11015	3	<u>Otv</u> 74 74	Loc Code	_	7&×	, .	·	X
D3690-1		Manufactured	No		17077	0 (Each	0.0000	1 	2 2	- M	1./	15/11
Glareshield	121 1221					B6	-	_	_	Λ Λ			1914
D3697-041 Tube Assembly		Manufactured	No				Each	2.0000		\mathcal{M}	L	6/11	16
,		,		Location ST241A		Loc	Qty 2	Loc Code		······································	• 	·	
					59243		2			&X	_		

Dart Ae	rospace l	_td							• •
W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						:			
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA	\:	Date:	
	Res	solution:	Dispositio	n:	_ QA: N/C CI	osed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCF	R)			
		Description of NC		Corrective Action Sect	ion B	Verific	ation	Approval	Approvai
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	k Section		Chief Eng	QC Inspector
								ĺ	

Picklist Print

Wednesday, October 27, 2010 4:03:51 PM

Work Order ID: 63352

Parent Item:

D3690-041

Parent Item Name: Glareshield Assembly



Start Date: 10/27/2010

Required Date: 11/11/2010

Start Qty: 2.00

Required Qty: 2.00

D3698-1

Manufactured No

No

Purchased

Each

6.0000

Support Angle

Location ST241A

Loc Qty

6 Each Loc Code

14,484.00

MS20426AD3-14

Rivet

Location ST316

4444 4533

Loc Code

Page 2

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
,												


Part No: D3690-041

Small FAS PAR #: _____ Fault Category: Thorne form

NCR: Yes No. DQA: ____ Date: _/0/z-vz_


Resolution: Acceptable Disposition: Use ps is.

NCR: 6		Description of NC		Corrective Action Section B	Verification	Approval	Approval	
DATE	STEP	Section A	Initial Action Description Chief Eng Chief Eng			Section C	Approval Chief Eng	QC Inspector
61.11.0 ₀	110	MS 20426AD3-6 TOO LONG. R.C. , PLASTIC AT HINIMUM TOLUMANCO.	ю.46	ACEPTABLE TO USE MSZ0486AD3-4 WHERE ALBUCABLE: M LD4374	m.10/11/17	10/11/15	W.11.16	ioluli8



Dart Aerospa	ace	Ltd
--------------	-----	-----

W/O:			WC	ORK ORDER CHAN	GES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	_ Date: _	
	Resolution: Disposition:				QA: N/C C	losed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORM	MANCE (NCF	₹)			
DATE	STEP	Description of NC			ection B	Sign & Verification		Approval	Approval
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Date		ion C	Chief Eng	QC Inspector
									-
									Ì
								; ;	
									1



D3690-041 GLARESHIELD ASSEMBLY

5

NOTES.
1) CENTER D3697-041 AND D3698-1 ON TO D3690-1
2) FINISH: PAINT D3690-041 ASSY FLAT BLACK USING BASF GLASURIT 22 LINE CODE SFA39.50 PER DART QSI 005 4.2
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED

5) IDERTIFICATION: ETCH WITH DART P/N D3690-041 & B/N ON INSIDE OF PART 5) WEIGHT: 2.98 lbs
6) MASK HATCHED AREAS (6 PLS) ON INSIDE OF THE PART PRIOR TO PAINTING

DESIGN **IRF** DART AEROSPACE LTD DRAWN RF HAWKESBURY, ONTARIO, CANADA CHECKED DRAWING NO. REV. C D3690 MFG. APPR Œ SHEET 2 OF 3 APPROVED TITLE SCALE GLARESHIELD ASSEMBLY

COPYRIGHT © 2008 BY DART ARROSPACE LTD

THIS SOCKENT BRIMATE AND COMPONING AND SUPPLIED OF THE EPIPESS COMPONENTED THAT IT IS

TOTAL SIZE OF AMERICAN PROPERTIES OF COMPONING TO AMERICAN PROPERTIES WITH THE THAT IS

TOTAL SIZE OF AMERICAN PROPERTIES OF COMPONING TO AMERICAN PROPERTIES WITH THE THAT IS


TOTAL SIZE OF AMERICAN PROPERTIES OF COMPONING TO AMERICAN PROPERTIES WITH THE THAT IS TH DE APPR. NTS DATE 08.09.02

3

8

Dart Aerospace Ltd

Dait Ac	. oopaoc	, Eta							•
W/O:			WO	RK ORDER CHANG	ES		,		
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:	Fault Cateç	jory:	_ NCR: Yes	No DQ	A:	Date: _	1
Resolution:		esolution:	Disposition):	_ QA: N/C C	losed:		Date: _	
NCR:			WORK ORDE	ER NON-CONFORMA	NCE (NCI	₹)			
		Description of NC	Corrective Action		Section B		cation	Approval	Approval
DATE	STEP	Section A	Initial Action Descri Chief Eng Chief Eng		Sign Date	Section C		Chief Eng	QC Inspector
•									
					<u>.</u>				
·									:
						,			-
	1								



TRIM PER MOLD SCRIBE LINES EXCEPT WHERE NOTE 3) FINISH: NONE 4) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED 5) UNITS: INCHES UNLESS OTHERWISE NOTED 6) BREAK SHARP EDGES: 0.005 TO 0.010 MAX 7) IDENTIFICATION: NONE 8) WEIGHT: 2.5 bs 9) MINIMUM THICKNESS AFTER FORMING IS 0.040

DESIGN	ŖF	DART AEROSPACE LTD				
DRAWN	₽F	HAWKESBURY, ONTARIO, CANADA				
CHECKED	لم	DRAWING NO. REV. C				
MFG. APPR.	RO	D3690 SHEET 3 OF 3				
APPROVED	NI.	TITLE SCALE				
DE APPR.		GLARESHIELD ASSEMBLY NTS				
DATE 08.0	9.02	COPYRIGHT © 2008 BY DART AEROSPACE LTD THIS DOCUMENT IS PRINATE AND CONFIDENTIAL AND SHAPIED OF THE CHIESE CO-DITION THAT IT IS NOT TO \$2.050.00 ANY PURPOSE ON CONFIDENCE TO JUNE OTHER PERSON WITHOUT				

Dart Ae	rospace	Lia							
W/O:			WO	RK ORDER CHANGES	3				
DATE STEP		PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No: PAR #:		Fault Category: NC			R: Yes No DQA: Date:				
			Disposition	QA: N/C CI	A: N/C Closed: Date:				
NCR:			WORK ORDE	R NON-CONFORMAN	CE (NCR)			
DATE	STEP	Description of NC	Corrective Action Section B			Verifica		tion Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector
					ŀ				
							<u>.</u>		
						-			
		Maria de la companio							
	1							1	